

TECHNICAL BULLETIN

FA-A-0438-A

[1/4]

Change in the External Appearance and Packaging Box of the MELSEC iQ-R Series Blank Cover Module

Date of IssueAugust 2024Relevant ModelsRG60

Thank you for your continued support of Mitsubishi Electric programmable controllers, MELSEC iQ-R series.

This technical bulletin informs you of the change in the external appearance and packaging box of the MELSEC iQ-R series blank cover module.

There is no impact on the general specifications, performance specifications, and functions of products due to the change.

1 RELEVANT MODEL

The relevant model is shown below.

Product	Model
MELSEC iQ-R series blank cover module	RG60

MITSUBISHI ELECTRIC CORPORATION

HEAD OFFICE: TOKYO BLDG., 2-7-3, MARUNOUCHI, CHIYODA-KU, TOKYO 100-8310, JAPAN NAGOYA WORKS: 1-14, YADA-MINAMI 5-CHOME, HIGASHI-KU, NAGOYA 461-8670, JAPAN

2 DETAILS ON THE CHANGE

This section describes the details of the change.

2.1 External Appearance of the Module

The shape of module body will be changed, and no more connector covers will be included in the package in the future.

Before change

Module body (Side)



• Module body (Rear)



Connector cover



After change

Module body (Side)




• Module body (Rear)



FA-A-0438-A

2.2 Packaging Box

The size of the packaging box will be changed.



3 REASONS FOR THE CHANGE

These changes are designed to reduce environmental impact as a part of our resource conservation activities (ISO14001).

4 CHANGEOVER PERIOD

The change will be applied to the products manufactured on or after September 2024.

External appearance change and packaging box change will be done at the same time.

Note that, depending on stock status, both the old and new products may be distributed in the market around that time.

TECHNICAL BULLETIN

FA-A-0438-A

REVISIONS

Version	Date of Issue	Revision
A	August 2024	First edition

TRADEMARKS

The company names, system names, and product names mentioned in this technical bulletin are either registered trademarks or trademarks of their respective companies.

In some cases, trademark symbols such as '[™]' or '[®]' are not specified in this technical bulletin.