No. 805E

MITSUBISHI ELECTRIC Inverter Sales and Service

Change to Improve Productivity for the FR-A846/ FR-F846 Inverters and the FR-LU08-01 Operation Panel (IP55 Model)

Thank you for your continued patronage of Mitsubishi Electric drive control products. For the FR-A846/FR-F846 inverters and the FR-LU08-01 operation panel (IP55 model), the gasket will be changed to improve productivity.


1. Products Affected

Product	Model
Inverter	FR-A846-00023(0.4K) to 03610(132K)-2-60L2
	FR-A846-00023(0.4K) to 03610(132K)-E2-60L2
	FR-A846-0.4K to 132K-1-60C3
	FR-A846-0.4K to 132K-E1-60C3
	FR-A846-00023(0.4K) to 03610(132K)-1-60C3
	FR-A846-00023(0.4K) to 03610(132K)-2-60C2
	FR-A846-00023(0.4K) to 03610(132K)-E1-60C3
	FR-A846-00023(0.4K) to 03610(132K)-E2-60C2
	FR-F846-00023(0.75K) to 03610(160K)-2-60L2
	FR-F846-00023(0.75K) to 03610(160K)-E2-60L2
	FR-F846-0.75K to 160K-1-60C3
	FR-F846-0.75K to 160K-E1-60C3
	FR-F846-00023(0.75K) to 03610(160K)-2-60C2
	FR-F846-00023(0.75K) to 03610(160K)-3-60C3
	FR-F846-00023(0.75K) to 03610(160K)-E2-60C2
	FR-F846-00023(0.75K) to 03610(160K)-E3-60C3
Operation panel	FR-LU08-01

2. Details of Change

To improve productivity, the gasket will be changed.

The change does not affect the quality, performance, or specifications of the products.



Date of issue		Title	Change to Improve Productivity for the FR-A846/FR-F846 Inverters and the FR-LU08-01 Operation Panel (IP55 Model)
---------------------	--	-------	--

3. Date of Change The change will be sequentially applied to the products manufactured in October 2024 or later.	